



Thomas C Thompson 09/516,655 Rafter Tie Plate Sheathing Tie




FIG. 1

not accepted
8-2. 10/5/05





FIG. 2

not accepted
E-L, 10/5/05



not accepted
EL, 10/5/05

FIG. 3





FIG. 4

not accepted
9/2, 10/5/05



Thomas C Thompson 09/516,655 Rafter Tie Plate Sheathing Tie




FIG. 5

not accepted
9-2. 10/5/05




FIG. 6

not accepted
Fl. 10/5/05